PRODUCT CHANGE NOTIFICATION (PCN)

PCN #: Telink-PCN-2023-018				Date: 2023/09/11	
Classification of Change:	**Change Impact on product:**			**Customer Notification:**	
☐ Critical ☑ Major ☐ Minor	Function Form Fit Quality or Reliability	☒No ☒No ☒No ☒No	☐Yes ☐Yes ☐Yes ☐Yes	☐ Approval Required ☑ Information Only	
Device affected: Please see the Telink P/N as below table.					

Subject: Embedded flashes change.

Telink P/N	Before Change		After Change	
	Supplier	**Flash P/N**	**Supplier**	**Flash P/N**
TLSR8656F512ET48、TLSR8258F512ET48、TLSR8258F512ET32、TLSR8253F512ET32、TLSR8251F512ET48、TLSR8251F512ET32、TLSR8251F512ET24、TLSR8656F512ET32、TLSR8250F512ET32、TLSR8250F512ET32Z、TLSR8277F512EL40、TLSR8273F512ET32、TLSR8270F512ET48、TLSR8236F512ET32、TLSR8355F512ET48、TLSR8272F512ET24、TLSR8238F512ET32、TLSR8355F512ET32、TLSR8273F512ET48、TLSR8271F512ET48、TLSR8271F512ET32	GigaDevice	GD25LD40CGIG	GigaDevice	GD25LD40EGIG-SC
TLSR8253F512AT32、TLSR8250F512GT32、TLSR8273F512GT32、TLSR8271F512GT32	GigaDevice	GD25LD40CGEG	GigaDevice	GD25LD40EGEG-SC
TLSR8258F1KET48A、TLSR8258F1KET32、TLSR8278F1KET48	GigaDevice	GD25LD80CGIG	GigaDevice	GD25LD80EGIG-SC
TLSR8258F1KAT32	GigaDevice	GD25LD80CGEG	GigaDevice	GD25LD80EGEG-SC
Change active from: Dec.2023				

Reason for the Change:

Flash supplier GigaDevice（hereinafter referred to as "GD"）informed that the original flash parts (as above before change) will be replaced by the new flash parts (as above after change), and the original flash parts will be EOL. To ensure supply chain sustainability and product delivery, Telink had qualified the new embedded flashes on the corresponding Telink chips, there are no differences between original and new flashes in terms of function/form/shape/ quality/reliability.

Action Required:

This change doesn't affect the function/form/shape/quality/reliability of the product, and customer doesn't need take

any measures. If you have any questions, please contact your Telink sales manager and FAE.

Product Identification:

The embedded flashes can be identified by chip marking as below.

Marking style	Flash code before and after the change		

		Before Change	After Change
	Telink P/N	GD Flash code	GD Flash code
	TLSR8656F512ET48、TLSR8258F512ET48、TLSR8258F512ET32、 TLSR8253F512ET32、TLSR8251F512ET48、TLSR8251F512ET32、 TLSR8251F512ET24、TLSR8656F512ET32、TLSR8250F512ET32、 TLSR8250F512ET32Z、TLSR8277F512EL40、TLSR8273F512ET32、 TLSR8270F512ET48、TLSR8275F512ET32、TLSR8236F512ET32、 TLSR8355F512ET48、TLSR8272F512ET24、TLSR8238F512ET32、 TLSR8355F512ET32、TLSR8273F512ET48、TLSR8271F512ET48、 TLSR8271F512ET32	L	BM
	TLSR8253F512AT32、TLSR8250F512GT32、TLSR8273F512GT32、 TLSR8271F512GT32	AF	BN
	TLSR8258F1KET48A、TLSR8258F1KET32、TLSR8278F1KET48	W	BO
	TLSR8258F1KAT32	U	BP

Marking style cell content:

```
•
TLSR8XXX
FXXXETXX
ZHCCYYWW
ABCDEF.GH
```

The 3rd and 4th characters in the 3rd line of the Marking stands for the Flash code(the red remark).

Further Contact：

Telink Semiconductor continually strives to deliver the highest quality, standards-compliant products to our valuable

customers. To meet your time-to-market needs, our focus is to first deliver a standards-compliant full functionality

device, while we continually improve the performance of our devices over time. We look forward to supporting your

use of these devices in your products. Further information is available at www.telink-semi.com and http://wiki.telink-

semi.cn or from your local Telink Semiconductor Representative.

Best Regards,

Liu Bi Xiang

QRA Senior Manager

Telink Semiconductor