





| Date | Version | Update |
|------------|---------|--|
| 2018-11-13 | V2.0 | update C9/C10/C11/L4 value |
| 2021-07-13 | V2.0 | Add TVS diode TT0321SB to the RF pin, PCB is not updated |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

| | | |
|-------------|------------------------|--------------|
| | | |
| Title | | |
| Telink-Semi | | |
| Size | Document Number | Rev |
| A | C1T139A3 | V2.0 |
| Date: | Tuesday, July 13, 2021 | Sheet 1 of 2 |







ANT




D9/D10 parts are reserved only for ESD protection, not necessary.

If the product has high requirements for ESD protection, please add those TVS components.


IO




LED




Buttom



Download



Power



| | | | |
|----------------------|-----------------------------|---------|-------------|
| | | | |
| Title Telink-Semi | | | |
| Size A4 | Document Number C1T139A3 | | Rev V2.0 |
| Date: | Tuesday, August 24, 2021 | Sheet 2 | of 2 |